#### ANALYTICAL REPORT

Prepared by Lockheed Martin Information Systems and Global Services/Environmental Services Scientific, Engineering, Response and Analytical Services

> Paulsboro Train Derailment Paulsboro, New Jersey

> > December 2012

EPA Work Assignment No. SERAS-001 LOCKHEED MARTIN Work Order SER40001 EPA Contract No. EP-W-09-031

> Submitted to S. Burchette **EPA-ERT** 2890 Woodbridge Avenue Edison New Jersey 08837

Analysis by: **ERT/SERAS** 

Analytical Support Leader

Prepared by:

B. Killeen QALOC Officer

J. Soroka

Validated by:

Program Manager

J. Soroka



#### Table of Contents

### **Topic**

Testing Laboratories Information Detailed Sample Information Introduction Case Narrative Summary of Abbreviations

### Section I

Results of the Analysis for VOC (ppbv) in Air Results of the Analysis for VOC ( $\mu g/m^3$ ) in Air Table 1.1b

#### Section II

Results of the LCS Analysis for VOC in Air

Results of the Duplicate Analysis for VOC in Air

Table 2.1

Table 2.2

#### Section III

Chain of Custody

### **Appendices**

Appendix A Data for VOC in Air X228

Appendix will be furnished on request.



### **TESTING LABORATORIES INFORMATION**

Analysis of Volatile Organic Compounds in Air, SERAS SOP# 1814, "Analysis of Volatile Organic Analysis (VOCs) in Air by Gas Chromatography/Mass Spectrometry (GC/MS)"

ERT/SERAS Laboratory 2890 Woodbridge Avenue Edison, NJ 08837

All analyses were performed according to our NELAP-approved quality assurance program. The test results meet the requirements of the current NELAP standard, where applicable, except as noted in the laboratory case narrative provided. Results are intended to be considered in their entirety and apply only to those analyzed and reported herein.

ERT/SERAS Laboratory is certified by the New Jersey Department of Environmental Protection, NELAP Laboratory Certification ID # 12023 for VOC analysis in air.

REPORT OF LABORATORY ANALYSIS



## **Detailed Sample Information**

## SERAS Sample #

## Field Sample #

R212009-01	40001-0010
R212009-02	40001-0012
R212009-03	40001-0013
R212009-04	40001-0014
R212009-05	40001-0015
R212009-06	40001-0016
R212009-07	40001-0017
R212009-08	40001-0018
R212009-09	40001-0019
R212009-10	40001-0020
R212009-11	40001-0021



1

#### Introduction

SERAS personnel, in response to WA# SERAS-001, provided analytical support for environmental samples collected from the Paulsboro Train Derailment in Paulsboro, New Jersey as described in the following table. The support also included QA/QC, data review and preparation of an analytical report containing analytical and QA/QC results.

The samples analyzed at SERAS were treated with procedures consistent with those specified in SERAS SOP #1008, *Sample Receiving, Handling and Storage* and SOP #1009, *Operation of Sample Refrigeration Units*.

Chain of Custody #	Number of Samples	Sampling Date	Date Received	Date Analyzed	Matrix	Analysis/ Method	Laboratory	Data Package
02-120912-111329- 0002	11	12/9/12	12/9/12	12/9-10/12	Air	VOC/SERAS SOP #1814	ERT/SERAS	X229

#### **Case Narrative**

Sampling was conducted as per the site-specific Quality Assurance Project Plan (QAPP) and analyzed by the analytical methods stated in the QAPP. The laboratory reported the data to three significant figures. Any other representation of the data is the responsibility of the user. Data were validated in accordance with the "Guidance for Labeling Externally Validated Laboratory Analytical Data for Superfund Use" using a Stage 4 Validation done manually (S4VM). All data validation flags have been inserted into the results tables. At the request of the Work Assignment Manager, the laboratory reported results for vinyl chloride.

#### VOCs in Soil Package X229

The data package was examined and found to be acceptable.

The results presented in this report only relate to the samples analyzed. All results are intended to be considered in their entirety. The Environmental Response Team/Scientific, Engineering, Response and Analytical Services laboratory is not responsible for utilization of less than the complete report.





#### **Summary of Abbreviations**

BFB Bromofluorobenzene

C Centigrade

CLP Contract Laboratory Program

COC Chain of Custody conc concentration cont continued

CRDL Contract Required Detection Limit
CRQL Contract Required Quantitation Limit

D (Surrogate Table) value is from a diluted sample and was not calculated

Dioxin Polychlorinated dibenzo-p-dioxins (PCDD) and Polychlorinated dibenzofurans (PCDF)

DFTPP Decafluorotriphenylphosphine

EMPC Estimated maximum possible concentration GC/MS Gas Chromatography/ Mass Spectrometry

IS Internal Standard

LCS Laboratory Control Sample

LCSD Laboratory Control Sample Duplicate

MDA Minimum Detectable Activity MS (BS) Matrix Spike (Blank Spike)

MSD (BSD) Matrix Spike Duplicate (Blank Spike Duplicate)

MW Molecular Weight

NA Not Applicable or Not Available
NAD Normalized Absolute Difference
NC Not Calculated

NR Not Requested/Not Reported

NS Not Spiked % D Percent Difference % REC Percent Recovery

SOP Standard Operating Procedure ppbv parts per billion by volume

ppm parts per million

pptv parts per trillion by volume
PQL Practical Quantitation Limit
PAL Performance Acceptance Limit
QA/QC Quality Assurance/Quality Control

QL Quantitation Limit RL Reporting Limit

RPD Relative Percent Difference RSD Relative Standard Deviation

SERAS Scientific, Engineering, Response and Analytical Services

SIM Selected Ion Monitoring

Sur Surrogate

TIC Tentatively Identified Compound

TCLP Toxicity Characteristic Leaching Procedure

VOC Volatile Organic Compound

Value exceeds the acceptable QC limits

$m^3$	cubic meter	g	gram	kg	kilogram	L	liter
μg	microgram	μL	microliter	mg	milligram	mL	milliliter
ng	nanogram	pg	picogram	pCi	picocurie	S	sigma

#### Data Validation Flags

J	Value is estimated	R	Value is unusable
I+	Value is estimated high (metals only)	11	Not detected

J- Value is estimated low (metals only) UJ Not detected and RL is estimated

N Presumptively present (Aroclors only)

Rev. 1/14/09



Results RL

ppbv

U 0.0300

ppbv



Page 1 of 1

0.321 0.0300

## Table 1.1a Result of the Analysis for VOC (ppbv) in Air WA# SERAS-001, Paulsboro Train Derailment

Results RL

ppbv ppbv

U 0.0300

Method: SERAS SOP#1814 SERAS Sample Number

Sample Number

Sample Location

Analyte

Vinyl Chloride

R212009-11 R212009-01 R212009-02 MethodBlank120912-01 P SystemBlank120912-01 N/A N/A 40001-0021 School 40001-0010 School 40001-0012 Jessup Results RL Results RL Results RL ppbv ppbv ppbv ppbv ppbv ppbv

0.0749 0.0300

Table 1.1a (cont) Result of the Analysis for VOC (ppbv) in Air WA# SERAS-001, Paulsboro Train Derailment

U 0.0150

Method: SERAS SOP#1814

SERAS Sample Number Sample Number Sample Location	4000	2009-03 01-0013 e Swan	4000	009-04 1-0014 orary	4000	009-05 1-0015 urch	40001	009-06 I-0016 School	40001	009-07 I-0017 ntua
Analyte	Results ppbv	<i>RL</i> ppbv	Results ppbv	<i>RL</i> ppbv	Results ppbv	<i>RL</i> ppbv	Results ppbv	<i>RL</i> ppbv	Results ppbv	<i>RL</i> ppbv
Vinyl Chloride	0.0866	0.0300	0.259	0.0300	0.736	0.0300	0.104	0.0300	0.195	0.0300

Table 1.1a (cont) Result of the Analysis for VOC (ppbv) in Air WA# SERAS-001, Paulsboro Train Derailment

Method: SERAS SOP#1814

SERAS Sample Number Sample Number Sample Location	R212009-08 40001-0018 Police Station		4000	1009-09 1-0019 thool	R212009-10 40001-0020 Firehouse
Analyte	Results ppbv	<i>RL</i> ppbv	Results ppbv	<i>RL</i> ppbv	Results <i>RL</i> ppbv ppbv
Vinyl Chloride	0.131	0.0300	0.0745	0.0300	0.0941 0.0300

## Table 1.1b Result of the Analysis for VOC (μg/m3) in Air WA# SERAS-001, Paulsboro Train Derailment

Method: SERAS SOP#1814

Page 1 of 1

SERAS Sample Number Sample Number Sample Location		ank120912-01 N/A	P SystemE	Blank120912-01 N/A	4000	009-11 1-0021 hool	4000	009-01 1-0010 nool	40001	009-02 1-0012 ssup
Analyte	Results µg/m3	<i>RL</i> μg/m3	Results µg/m3	RL µg/m3	Results µg/m3	<i>RL</i> μg/m3	Results µg/m3	<i>RL</i> µg/m3	Results µg/m3	<i>RL</i> μg/m3
Vinyl Chloride	U	0.0767	U	0.0767	U	0.0383	0.191	0.0767	0.822	0.0767

## Table 1.1b (cont) Result of the Analysis for VOC (µg/m3) in Air WA# SERAS-001, Paulsboro Train Derailment

Method: SERAS SOP#1814

SERAS Sample Number Sample Number Sample Location	400	2009-03 01-0013 te Swan	400	2009-04 01-0014 .ibrary	4000	009-05 1-0015 urch	4000	009-06 1-0016 School	40001	009-07 -0017 ntua
Analyte	Results µg/m3	RL µg/m3	Results µg/m3	RL μg/m3	Results µg/m3	<i>RL</i> μg/m3	Results µg/m3	<i>RL</i> µg/m3	Results µg/m3	<i>RL</i> μg/m3
Vinyl Chloride	0.221	0.0767	0.661	0.0767	1.88	0.0767	0.267	0.0767	0.498	0.0767

## Table 1.1b (cont) Result of the Analysis for VOC ( $\mu$ g/m3) in Air WA# SERAS-001, Paulsboro Train Derailment

Method: SERAS SOP#1814

SERAS Sample Number	400	2009-08	R212009-09		R212009-10		
Sample Number		01-0018	40001-0019		40001-0020		
Sample Location		e Station	School		Firehouse		
Analyte	Results	<i>RL</i>	Results	<i>RL</i>	Results	<i>RL</i>	
	µg/m3	µg/m3	µg/m3	μg/m3	µg/m3	μg/m3	
Vinyl Chloride	0.335	0.0767	0.190	0.0767	0.240	0.0767	



# Table 2.1 Results of the LCS Analysis for VOC in Air WA# SERAS-001, Paulsboro Train Derailment

Sample ID: LCS 12/09/12

Page 1 of 1

Analyte	LCS Spike Amount ppbv	LCS Recovered ppbv	% Recovery	QC Limits % Recovery
Vinyl Chloride	1.00	1.03	103	54 - 149

<sup>\*</sup>Indicates out of the criteria

This report shall not be reproduced, except in full, without the written consent of ERT/SERAS Laboratory



SERAS-001-DAR-121012 5



# Table 2.2 Results of the Duplicate Analysis for VOC in Air WA# SERAS-001, Paulsboro Train Derailment

Page 1 of 1

Sample id: 40001-0013

Analyte	Initial Analysis ppbv	Duplicate Analysis ppbv	RPD	QC Limit RPD
Vinyl Chloride	0.0866	0.0913	5	≤25

Table 2.2 (cont) Results of the Duplicate Analysis for VOC in Air WA# SERAS-001, Paulsboro Train Derailment

Sample ID: 40001-0016

Analyte	Initial Analysis ppbv	Duplicate Analysis ppbv	RPD	QC Limit RPD
Vinyl Chloride	0.104	0.109	5	≤25

Table 2.2 (cont) Results of the Duplicate Analysis for VOC in Air WA# SERAS-001, Paulsboro Train Derailment

Sample ID: 40001-0020

Analyte	Initial Analysis ppbv	Duplicate Analysis ppbv	RPD	QC Limit RPD
Vinyl Chloride	0.0941	0.0921	2	≤25

REPORT OF ANALYSIS

This report shall not be reproduced, except in full, without the written consent of ERT/SERAS Laboratory



SERAS-001-DAR-121012 6

USEPA

DateShipped: 12/9/2012
CarrierName:
AiffillNo:

CHAIN OF CUSTODY RECORD

Site #: 40001

Contact Name: Colleen Steffensen

Contact Phone: 609-865-6650

No: 2-120912-111329-0002

Cooler #: 1

Lab: ERT/SERAS

Lab Phone: 732-321-4200

#I-DA PO DO	Sample #	Location	Analyses	Matrix	Collected	Numb Cont	Container	Pump #	OrificeID	Start Pressu re	Pressu
(P)	40001-0010	School	TO-15	Air	12/9/2012	1	6-L summa	121	13931		-2
172	40001-0012	Jessup	TO-15	Air	12/9/2012	1	6-L summa	202	13963	-30	-
53	40001-0013	White Swan	TO-15	Air	12/9/2012	1	6-L summa	236	13767	-30	
724	40001-0014	Library	TO-15	Air	12/9/2012	1	6-L summa	1134	13789	-30	- 3
15	40001-0015	Church	TO-15	Air	12/9/2012	1	6-L summa	129	13913	-30	-3.5
6	40001-0016	High School	TO-15	Air	12/9/2012	1	6-L summa	215	13762	-30	
17	40001-0017	Mantua	TO-15	Air	12/9/2012	1	6-L summa	De 98	014011	-30	
8	40001-0018	Police Station	TO-15	Air	12/9/2012	1	6-L summa	102	14032	-30	-2
9	40001-0019	School	TO-15	Air	12/9/2012	1	6-L summa	115	13949	-30	
0	40001-0020	Firehouse	TO-15	Air	12/9/2012	1	6-L summa	98 92	13959	-30	-2
il	40001-0021	School	70-15	Blank	12/8/2012	1	6-L summa	8	_	-30	-30
				RD)	•						

	SAMPLES TRANSFERRED FROM
Special Instructions:	CHAIN OF CUSTODY#

Items/Reason	Relinquished by	Date	Received by	Date	Time	Items/Reason	Relinquished By	Date	Received by	Date	Time
Ace/ Anolysi	0	12/9/12	Mayly	12/0/12	1520	All Analysis	Marsal	12/9/12	1/ Red	12/9/12	17:15
							V (		10		